

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

FIG. 1



TDS Data ($M_z = 18$)

CVD SiOC



Porous MSQ






FIG. 2

FIG. 3



Initial



After Cleaning

pH Stability (Bath-life)




FIG. 4

FIG. 5




FIG. 6






FIG. 7

Top Views of Via Arrays

SEM image and AES map , 45 sec via open process




SEM



Cu AES Map

FIG. 8

Cu Concentration Scan: Dynamic FE Auger As a function of position on via sidewall



Control: Reference scan adjacent to via